


www.AVstumpfl.com

SET UP SUPPORT FOR LEGS

ANLEITUNG



MONTAGEHILFE FÜR FUSSTÜTZEN



INSTRUCTIONS

1 Set consisting of: 4x round bar holder for easy mounting of the legs by one person only.

2 - 4 The holders have to be pushed from the inner side with the upper fork over the projection screen frame. The top pin is placed between the projection surface and the frame. The position of the holders must be chosen, depending on the leg type and set-up height, in a way that an interference-free screwing of the wing screws can be guaranteed. A slight inclination of the holder gives the system the required stability.

5 - 8 Unfold the leg according to the pictures and place it on the holder so that the vertical bar of the leg (connection holes) lies on the middle arm and the not yet extended telescopic support below it.

9 - 11 Now the leg can be brought in set-up height position as well as the screw holes match with the mounting points on the frame, by one person only. The wing screws can be tightened easily without holding the frame and leg in position.

12 - 15 After having attached the legs to the frame the holders have to be removed by rotating them according to the pictures by 90°.



AV Stumpfl GmbH | Mitterweg 46 | 4702 Wallern
AVstumpfl@AVstumpfl.com | www.AVstumpfl.com | +43 7249 42811

Änderungen dienen dem technischen Fortschritt und bleiben vorbehalten.
We reserve the right to make modifications in the interest of technical progress.